

# Practical Experience with SFRA Technique

Rafal Zaleski  
Principal Transformer Engineer  
Doble Engineering

*ALTANOVA, a Doble Engineering Company, provides diagnostic solutions to utilities and industries to improve the performance of their electrical assets through portable testing equipment, advanced monitoring systems, and professional services.*




# Altanova History

- 1938 I.S.A. Istrumentazioni Sistemi Automatici S.r.l. is established in Taino ITALY
- 1999 TECHIMP was born as a spin-off from the University of Bologna ITALY.
- 2017 I.S.A. and TECHIMP merge giving birth to the ALTANOVA GROUP
- 2019 INTELLISAW joins ALTANOVA GROUP
- 2021 ALTANOVA GROUP becomes part of ESCO Technology Group and joins the Doble Engineering Company, as part of the USG division.



# Doble History

## 100 YEARS OF SERVICE TO THE ELECTRIC UTILITY INDUSTRY



# Altanova Today



**100**  
COUNTRIES



**12** GLOBAL  
FACILITY  
LOCATIONS



**150+**  
EMPLOYEES



**150+**  
SALES PARTNERS



**5550+**  
CUSTOMERS GLOBALLY



Part of ESCO Technologies'  
Utility Solutions Group

## PRODUCT BRANDS



# Our Solutions

## Electrical Test Equipment

Essential for day-to-day maintenance tests of electrical assets. Useful in specific phases of the asset lifecycle:

- Procure
- Operate
- Maintain
- Decommission.

## Professional Services

Diversified offer according to the electrical asset lifecycle:

- Installation and commissioning
- Diagnostic test
- Data analysis
- Consultancy
- Training.



## Monitoring Systems

Shift from a time-based maintenance to a condition-based maintenance.

Focus on predictive maintenance and shift in focus from electric asset value cost to network outage costs.

Strong evolution of digitalization trend in the power industry.



# Testing And Monitoring Solutions For:

- Power transformers
- Circuit breakers
- HV gas insulated switchgears
- MV/HV/EHV cables
- MV/LV switchgears
- Batteries
- Current & voltage transformers
- Protective relays
- Meters and transducers
- Rotating machines
- Variable speed drives
- Overhead lines



# SFRA Technique

1. Introduction
2. Influencing Factors
3. Importance of Reference Results
4. Case Study






# Introduction

Frequency Response Analysis (FRA) is commonly used to assess the mechanical integrity of transformer active part

Normally performed during the following:


- Factory fingerprint before transport to site
- Short circuit test
- Site fingerprint/diagnostic after transportation prior to commissioning
- Relocation and installation
- Routine diagnostic protocol
- After transformer alarm or trip
- After through fault, lightning, seismic event

Comparative test – relies on compared responses being **measured in the same way** and in the **same transformer condition**.




# International Collaborations (2008 – 2020)


## Cigre WG A2.26




## IEEE WG C57.149



## IEC PT 60076-18



## Cigre A2.53



**ALTANOVA**  
A DOBLE COMPANY



# Influencing Factors




# Effect of core magnetization




Low frequency variation is severe - but identifiable

# Effect of tap position



Tap position is one of the most obvious factors influencing result


# Nominal tap position (N)



(N) from (N-1) is not the same as (N) from (N+1)




# Effect of state of other winding




Impact of HV tap position on LV test

# Effect of state of other winding



Impact of HV series/parallel switch on LV test


# Effect of state of other winding



Impact of LV delta state on HV test



# Effect of internally grounded delta winding



Impact of internally earthed delta winding on responses of other windings

# Experiment with delta winding



Impact of state of delta winding on responses of other windings



# Effect of insulating liquid




Measurement in fully assembled condition and in transportation condition





# Effect of long GIS busbar



# Effect of missing core earth



# Effect of poor grounding



Can you spot difference between the two grounding braids?

# Effect of poor grounding



...one was not correctly earthed





# ALTANOVA

A DOBLE COMPANY



## Importance of Good Reference Results

# Importance of good reference results


The SFRA results not always give easy to interpret results eg. completely aligned responses of three phases. Although in some cases experience plays important role and allows to recognize certain situations, sometimes additional reference results are extremely helpful in interpretation.

Such reference can be usually taken from:

- Previous results
- Sister unit


It is important to obtain the same test setup as was used for reference results in order to use them.

# Importance of good reference results




Suspicious difference was measured at LV side. Sister transformer was available to obtain reference but it was connected to HV cables.

# Importance of good reference results



Small distribution  
transformer





# ALTANOVA

A DOBLE COMPANY

   MORGAN  
SCHAEFFER  PHENIX  
TECHNOLOGIES   Vanguard Instruments

## SFRA Examples




# Shorted turns



Let's start with something easy.


750MVA, 380/230/13.8kV autotransformer YNay0d11, failed in service

# Movement of Single Turns




So is this a good transformer? It tripped from service due to flashover across contacts of A phase OLTC selector.

# Movement of Single Turns




So is this a good transformer? It tripped from service due to flashover across contacts of A phase OLTC selector.

# Movement of Single Turns



So is this a good transformer? It tripped from service due to flashover across contacts of A phase OLTC selector.


# Movement of Single Turns



So is this a good transformer? It tripped from service due to flashover across contacts of A phase OLTC selector.



# Movement of Single Turns



Luckily it was possible to see damage through inspection hole.  
Scrapping confirmed slight winding deformation on A phase

# Axial Collapse

Initial symptoms

35 year old 400/132 kV 240 MVA auto-transformer

10:53 a.m. Monday 5th November 2001

**Buchholz alarm**

Transformer **switched out for investigation**

Analysis of **Buchholz gas** and **main tank oil** indicated **serious fault**


No abnormal system events

Transformer was operating at 80% loading

**Hardly non-conclusive electrical test results, but...**


# Axial Collapse

8 / 1 1 / 0 1



# Axial Collapse


22/11/94



Previous results

# Axial Collapse

28/07/94



Sister unit failed in service



# Axial Collapse



# Buckling Deformation


Transformer details:

- 375/750MVA ONAN/ODAF
- 400/275/13kV autotransformer
- No taps
- Built 1966
- Deterioration in DGA results
- Removed from service for investigation



# Buckling Deformation

One of gas increases coincided with CT failure



DGA showed three potentially damaging events

# Buckling Deformation

T4673			
	A phase	B phase	C phase
Main windings to earth, CH	4,405 pF 0.51 %	3,634 pF 0.56 %	4,294 pF 0.52 %
Main windings to tertiary, CHT	8,786 pF 0.55 %	8,711 pF 0.56 %	8,525 pF 0.56 %
Tertiary winding to earth, CT	17,924 pF 0.52 %		


Sister  
transformer

Suspect  
transformer

T4971			
	A phase	B phase	C phase
Main windings to earth, CH	4,246 pF 0.75 %	3,368 pF 0.51 %	4,273 pF 0.62 %
Main windings to tertiary, CHT	8,277 pF 0.42 %	<b>5,775 pF</b> <b>1.91 %</b>	9,030 pF 0.54 %
Tertiary winding to earth, CT	<b>20,668 pF</b> 0.46 %		

Significant difference in capacitance and power factor were noted for phase B

# Buckling Deformation



Also a significant difference in frequency response was noted for phase B




# Buckling Deformation




# Tap Winding Movement

- 275/33kV 120MVA YNd1 transformer feeding steelworks suffered flashover between taps while on 'hot standby'
- Barrier board between tap-changer and main tank broken
- SFRA tests indicated movement for tap winding:
  - ✓ **Difference for Blue phase at Tap 1 (taps 'all-in'), but not at Tap 10 ( 'all-out')**
  - ✓ **Compared responses with sister reference transformer**
  - ✓ **Note faulty transformer was without oil, while reference was oil filled**
- Internal inspection confirmed conductor tilting for Blue phase tap winding
- Special SFRA Tests showed possibility of internal resonant over-voltage between taps involved in flashover for switching surge at HV line terminal


# Tap 10 HV SFRA for faulty transformer




# Tap 10 HV SFRA for reference transformer



# Tap 1 HV SFRA for faulty transformer



# Tap 1 HV SFRA for reference transformer





# Broken tap-changer barrier board



# Flashover damage between Blue phase tap leads





# Internal View



# Conclusions

- Reference results if available, can greatly support interpretation of results. This can help either to confirm winding damage or to clear doubts regarding suspicious traces
- It is important to be aware of number of different factors which can affect the measurement, eg. tap position, state of stabilizing winding. Results obtained in different conditions may not make good reference.
- Little difference can still mean dangerous deformation but at the same time, large differences can be caused by factors other than winding damage. This makes interpretation more difficult.



# ALTANOVA

A DOBLE COMPANY

doble isa MS MORGAN SCHAEFFER PHENIX TECHNOLOGIES TECHMP Vanguard Instruments

# Thank you!

Rafal Zaleski  
Principal Transformer Engineer  
Doble Engineering